

Datalogic Heron D130

Configuration Sheet

Add Enter After Scan



Exit and Save Configuration

